DRAFT DATA – SWAMP Labor Day 2008 Bacteria Monitoring

Description of Sample Site:	Spanish Creek at USFS campground off of Hwy 70		
SWAMP Site ID:	518PLU900		
Watershed:	Spanish Creek Watershed		
County:	Plumas		
Longitude:	-120.961110		
Latitude:	40.007420		

Constituent	Water Quality Guideline	Wednesday August 27, 2008	Sunday August 31, 2008	Wednesday September 3, 2008
E. coli (MPN/100 mL)	<235 MPN/100mL (EPA Contact Recreation Guideline)	20.1	18.9	10.9
Electrical Conductivity (umhos/cm)	≤900 umhos/cm (Secondary Maximum Contaminant Level)	208.4	n/a	198.2
рН	6.5-8.5 (Basin Plan Objective)	7.14	n/a	7.67
Temperature (° Celcius)	≤20 °C (Basin Plan Objective for Bay-Delta)	20.7	n/a	14.5

[•]NOTES: Shaded table cells contain values that do not meet the water quality guidelines.

August 27, 2008 12:06PM

August 31, 2008 13:23PM

September 3, 2008 10:41AM

No image available



No image available

- Flow Data for Spanish Crk Below Blackhawk Crk at Keddie (SPK

ca.

15

Sample Time

The Central Valley Regional Water Quality Control Board (CVRWQCB) conducted a region-wide Recreation Beneficial Use study, using *E. coli* as an indicator, with a guideline of 235 MPN/100mL. Funding for this study was made possible through the Surface Water Ambient Monitoring Program (SWAMP. Assistance with field collection was provided by a number of local watershed groups. Summary sheets for all sites included in this study can be found at:

http://www.waterboards.ca.gov/centralvalley/water_issues/water_quality_studies/surface_water_ambient_monitoring/index.shtml







